

## No Sound After Windows Update ( April 21)

solved with the following.

1. Select IDT High Definition Audio CODEC on Device Manager.
2. Select Driver tab.
3. Click Update Driver... button.
4. Select -> Browse my computer for driver software.
5. Select -> Let me pickup a list of device drivers on my computer.
6. Select **High Definition Audio Device** (Not IDT High Def... this is important.) and click Next.  
Appears Warning message, but reply Yes.
7. ! Windows has successfully update your driver software.

Credit this forum link

[https://answers.microsoft.com/en-us/insider/forum/insider\\_wintp-insider\\_devices/idt-high-definition-audio-codec-not-working-on/570a5038-e48e-43f3-af75-95da61447c87](https://answers.microsoft.com/en-us/insider/forum/insider_wintp-insider_devices/idt-high-definition-audio-codec-not-working-on/570a5038-e48e-43f3-af75-95da61447c87)

PDF Downloaded from cgwells.co.uk